



ARAHAN KERJA

NO. ARAHAN KERJA

WO-08-0038

TARIKH

23.08.2024

ARAHAN DARI	VENDOR	BAHAGIAN
KUDR	KAD	GIS

Kepada		Butiran Kerja		
KUMPULAN ASIA DEBUT SDN BHD		PROJEK SISTEM PENGAGIHAN GAS ASLI KE TELUK INTAN FL STAGE 1/24 (PAKEJ 1) TELUK INTAN, PERAK DARUL RIDZUAN		
NO.	BUTIRAN	JARAK (M)	LOKASI	
1	Mohon Sediakan Pelan Izin Lalu (PIL) dan data lot	12828		
	Koordinat Mula	Koordinat Akhir	Jarak	Nama Jalan
GV	3.92025, 100.95	3.939835, 100.961982	2500	JALAN KLANG - TELUK INTAN - BIDOR (5) (JKR BAGAN DATUK)
HDD	3.962106, 100.978743	3.96269, 100.97923	80	JALAN KLANG - TELUK INTAN - BIDOR (5) (JKR HILIR PERAK)
GV	3.939835, 100.961982	3.962106, 100.978743	3276	JALAN KLANG - TELUK INTAN - BIDOR (5) (JKR HILIR PERAK)
HDD	3.96269, 100.97923	3.963675, 100.980071	150	JALAN MAHARAJALELA (58) (JKR HILIR PERAK)
GV	3.962762, 100.97917	3.995525, 101.004871	5070	JALAN MAHARAJALELA (58) (JKR HILIR PERAK)
GV	3.995525, 101.004871	3.984583, 101.015806	1752	JALAN TEBUK BANJAR (JKR HILIR PERAK)
HDD	3.981284, 100.989189	3.981284, 100.989189	0	SUNGAI BATAK RABIT
HDD	3.932262, 100.957628	3.932262, 100.957628	0	SUNGAI BULUH
HDD	3.921958, 100.951343	3.921958, 100.951343	0	SUNGAI IPEL
HDD	3.947713, 100.967651	3.947713, 100.967651	0	SUNGAI PAK KOLEK
HDD	3.93762, 100.960397	3.93762, 100.960397	0	SUNGAI (TIADA NAMA)

NOTA :

- Sila rujuk dalam lampiran Pelan Izin Lalu

CATATAN:

[Signature]

TANDATANGAN : PENGURUS KORIDOR NEGERI

23.8.24

Tarikh



ARAHAN KERJA

NO. ARAHAN KERJA
WO-08-0038

TARIKH
23.08.2024


ARAHAN DARI	VENDOR	BAHAGIAN
KUDR	AGF	PENGURUS OPERASI

Kepada	Butiran Kerja			
ASIA GLOBAL FIELD SDN BHD	PROJEK SISTEM PENGAGIHAN GAS ASLI KE TELUK INTAN FL STAGE 1/24 (PAKEJ 1) TELUK INTAN, PERAK DARUL RIDZUAN			
NO.	BUTIRAN	JARAK (M)		LOKASI
1	Mohon Atur Lawatan Tapak	12828		
	Koordinat Mula	Koordinat Akhir	Jarak	Nama Jalan
GV	3.92025, 100.95	3.939835, 100.961982	2500	JALAN KLANG - TELUK INTAN - BIDOR (5) (JKR BAGAN DATUK)
HDD	3.962106, 100.978743	3.96269, 100.97923	80	JALAN KLANG - TELUK INTAN - BIDOR (5) (JKR HILIR PERAK)
GV	3.939835, 100.961982	3.962106, 100.978743	3276	JALAN KLANG - TELUK INTAN - BIDOR (5) (JKR HILIR PERAK)
HDD	3.96269, 100.97923	3.963675, 100.980071	150	JALAN MAHARAJALELA (58) (JKR HILIR PERAK)
GV	3.962762, 100.97917	3.995525, 101.004871	5070	JALAN MAHARAJALELA (58) (JKR HILIR PERAK)
GV	3.995525, 101.004871	3.984583, 101.015806	1752	JALAN TEBUK BANJAR (JKR HILIR PERAK)
HDD	3.981284, 100.989189	3.981284, 100.989189	0	SUNGAI BATAK RABIT
HDD	3.932262, 100.957628	3.932262, 100.957628	0	SUNGAI BULUH
HDD	3.921958, 100.951343	3.921958, 100.951343	0	SUNGAI IPEL
HDD	3.947713, 100.967651	3.947713, 100.967651	0	SUNGAI PAK KOLEK
HDD	3.93762, 100.960397	3.93762, 100.960397	0	SUNGAI (TIADA NAMA)

NOTA :

- Sila rujuk dalam lampiran Pelan Izin Lalu

CATATAN:


 TANDATANGAN: PENGURUS KORIDOR NEGERI

23. 8. 24
 Tarikh