

## ARAHAN KERJA

**NO. ARAHAN KERJA**  
**WO-04-0367**

**TARIKH**  
**28.04.2025**

<b>ARAHAN DARI</b> <b>KUDR</b>	<b>VENDOR</b> <b>AGF</b>	<b>BAHAGIAN</b> <b>PENGURUS OPERASI</b>
-----------------------------------	-----------------------------	--

Kepada		Butiran Kerja		
ASIA GLOBAL FIELD SDN BHD		MSVT (D-TEL-S24-4438) - MEWUJUDKAN PENCAWANG BARU BAGI MENGATASI LOW VOLTAGE DI KUNCI AIR 4 (LABU KUBONG), CHENDERONG BALAI		
NO.	BUTIRAN	JARAK (M)		LOKASI
1	Mohon Atur Lawatan Tapak	<u>355</u>		
	<b>Koordinat Mula</b>	<b>Koordinat Akhir</b>	<b>Jarak</b>	<b>Nama Jalan</b>
HDD	4.0870756, 101.03669746	4.08802509, 101.03662818	106	JALAN SUNGAI MANIK
HDD	4.08718933, 101.036619	4.08728247, 101.03711907	57	JALAN SUNGAI MANIK
HDD	4.08748764, 101.03653993	4.08728247, 101.03711907	95	JALAN SUNGAI MANIK
HDD	4.08794499, 101.03658093	4.08728247, 101.03711907	97	JALAN SUNGAI MANIK

**NOTA :**

- Sila rujuk dalam lampiran Pelan Izin Lalu

CATATAN:

-----  
-----  
-----



TANDATANGAN : PENOLONG PENGURUS KORIDOR NEGERI

28/4/2025

Tarikh

## ARAHAN KERJA

NO. ARAHAN KERJA

**WO-04-0367**

TARIKH

**28.04.2025**

ARAHAN DARI	VENDOR	BAHAGIAN
KUDR	KAD	GIS

Kepada		Butiran Kerja		
KUMPULAN ASIA DEBUT SDN BHD		MSVT (D-TEL-524-4438) - MEWUJUDKAN PENCAWANG BARU BAGI MENGATASI LOW VOLTAGE DI KUNCI AIR 4 (LABU KUBONG), CHENDERONG BALAI		
NO.	BUTIRAN	JARAK (M)	LOKASI	
1	Mohon Sediakan Pelan Izin Lalu (PIL) dan data lot	<u>355</u>		
	<b>Koordinat Mula</b>	<b>Koordinat Akhir</b>	<b>Jarak</b>	<b>Nama Jalan</b>
HDD	4.0870756, 101.03669746	4.08802509, 101.03662818	106	JALAN SUNGAI MANIK
HDD	4.08718933, 101.036619	4.08728247, 101.03711907	57	JALAN SUNGAI MANIK
HDD	4.08748764, 101.03653993	4.08728247, 101.03711907	95	JALAN SUNGAI MANIK
HDD	4.08794499, 101.03658093	4.08728247, 101.03711907	97	JALAN SUNGAI MANIK

**NOTA:**

- Sila rujuk dalam lampiran Borang Kelulusan Izin Lalu

CATATAN:

-----  
-----  
-----

  
TANDATANGAN : PENOLONG PENGURUS KORIDOR NEGERI

**KORIDOR UTILITI DARUL RIDZUAN (KUDR)**

28/4/2025  
Tarikh