



ARAHAN KERJA

NO. ARAHAN KERJA
WO-12-0977

TARIKH
16.12.2025

ARAHAN DARI KUDR	VENDOR AGF	BAHAGIAN PENGURUS OPERASI
---------------------	---------------	------------------------------

Kepada		Butiran Kerja		
ASIA GLOBAL FIELD SDN BHD		MSVT RECONFIGURE FEEDER ISTANA KINTA UNTUK MEWUJUDKAN N-1 SOURCE		
NO.	BUTIRAN	JARAK (M)		LOKASI
1	Mohon Atur Lawatan Tapak	<u>350</u>		
	Koordinat Mula	Koordinat Akhir	Jarak	Nama Jalan
HDD	4.582328, 101.098429	4.582579, 101.098505	30	JALAN RAJA PERMAISURI BAINUN (JALAN KAMPAR)
CW	4.582579, 101.098505	4.584741, 101.100339	320	PERSIARAN KAMPAR

NOTA :


1. Sila rujuk dalam lampiran Pelan Izin Lalu

CATATAN:

TANDATANGAN : PENGURUS KORIDOR NEGERI

17.12.25

Tarikh



ARAHAN DARI	VENDOR	BAHAGIAN
KUDR	KAD	GIS

Kepada		Butiran Kerja		
KUMPULAN ASIA DEBUT SDN BHD		MSVT RECONFIGURE FEEDER ISTANA KINTA UNTUK MEWUJUDKAN N-1 SOURCE		
NO.	BUTIRAN	JARAK (M)		LOKASI
1	Mohon Sediakan Pelan Izin Lalu (PIL) dan data lot	<u>350</u>		
	Koordinat Mula	Koordinat Akhir	Jarak	Nama Jalan
HDD	4.582328, 101.098429	4.582579, 101.098505	30	JALAN RAJA PERMAISURI BAINUN (JALAN KAMPAR)
CW	4.582579, 101.098505	4.584741, 101.100339	320	PERSIARAN KAMPAR

NOTA :

- Sila rujuk dalam lampiran Borang Kelulusan Izin Lalu

CATATAN:

TANDATANGAN : PENGURUS KORIDOR NEGERI

KORIDOR UTILITI DARUL RIDZUAN (KUDR)

17.12.25

Tarikh