

ARAHAN DARI	VENDOR	BAHAGIAN
KUDR	AGF	PENGURUS OPERASI

Kepada	Butiran Kerja
ASIA GLOBAL FIELD SDN BHD	PER: PERMOHONAN BAGI MENDAPATKAN KEBENARAN LALUAN UNTUK LALUAN KABEL GANTIAN OPTIK DI RIZAB JALAN SULTAN NAZRIN SHAH, PERAK (PMU JLN GOENG - PPU GUNUNG RAPAT)

NO.	BUTIRAN	JARAK (M)	LOKASI
1	Mohon Atur Lawatan Tapak	<u>7208</u>	
	Koordinat Mula	Koordinat Akhir	Jarak
	Nama Jalan		
HDD	4.574011, 101.123449	4.572999, 101.12512	240
HDD	4.553216, 101.116525	4.553216, 101.116525	180
HDD	4.553216, 101.116525	4.554655, 101.115673	200
HDD	4.576623, 101.141281	4.576638, 101.143327	205
HDD	4.576623, 101.141281	4.576522, 101.14308	205
HDD	4.55777, 101.113134	4.559399, 101.112357	225
HDD	4.559399, 101.112357	4.561532, 101.112719	250
HDD	4.561532, 101.112719	4.563774, 101.113177	250
HDD	4.563774, 101.113177	4.565834, 101.11359	245
HDD	4.565834, 101.11359	4.568092, 101.113777	225
HDD	4.568092, 101.113777	4.569387, 101.113611	150
HDD	4.569387, 101.113611	4.570277, 101.115626	250
HDD	4.570277, 101.115626	4.571224, 101.117629	250
HDD	4.571224, 101.117629	4.572197, 101.119588	250
HDD	4.572197, 101.119588	4.573059, 101.121396	235
HDD	4.573059, 101.121396	4.574011, 101.123449	260
HDD	4.554655, 101.115673	4.556105, 101.114513	215
HDD	4.556105, 101.114513	4.55777, 101.113134	250
HDD	4.572221, 101.127191	4.571443, 101.129195	250
HDD	4.572221, 101.127191	4.572221, 101.127191	250
HDD	4.577716, 101.139773	4.577985, 101.140887	135
HDD	4.577829, 101.138218	4.577716, 101.139773	180
HDD	4.577985, 101.140887	4.576623, 101.141281	170
HDD	4.569108, 101.136901	4.569165, 101.138296	165
HDD	4.569165, 101.138296	4.571323, 101.13828	250
HDD	4.570175, 101.130983	4.56933, 101.132812	235
HDD	4.56933, 101.132812	4.568991, 101.134765	235
HDD	4.568991, 101.134765	4.569108, 101.136901	245
HDD	4.571443, 101.129195	4.570175, 101.130983	258
HDD	4.573447, 101.138227	4.575566, 101.138228	245
HDD	4.571323, 101.13828	4.573447, 101.138227	245
HDD	4.575566, 101.138228	4.577829, 101.138218	260

NOTA :

1. Sila rujuk dalam lampiran Pelan Izin Lalu

CATATAN:


 TANDATANGAN: PENGURUS KORIDOR NEGERI

5/12/24
 Tarikh



ARAHAN KERJA

NO. ARAHAN KERJA
WO-12-0176

TARIKH
05.12.2024

ARAHAN DARI	VENDOR	BAHAGIAN
KUDR	KAD	GIS

Kepada	Butiran Kerja
KUMPULAN ASIA DEBUT SDN BHD	PER: PERMOHONAN BAGI MENDAPATKAN KEBENARAN LALUAN UNTUK LALUAN KABEL GANTIAN OPTIK DI RIZAB JALAN SULTAN NAZRIN SHAH, PERAK (PMU JLN GOENG - PPU GUNUNG RAPAT)


NO.	BUTIRAN	JARAK (M)	LOKASI	
1	Mohon Sediakan Pelan Izin Lalu (PIL) dan data lot	7208		
	Koordinat Mula	Koordinat Akhir	Jarak	
			Nama Jalan	
HDD	4.574011, 101.123449	4.572999, 101.12512	240	JALAN KERJASAMA
HDD	4.553216, 101.116525	4.553216, 101.116525	180	JALAN PESIARAN SIBER 1
HDD	4.553216, 101.116525	4.554655, 101.115673	200	JALAN PESIARAN SIBER 1
HDD	4.576623, 101.141281	4.576638, 101.143327	205	JALAN RAPAT PERMAI 18A
HDD	4.576623, 101.141281	4.576522, 101.14308	205	JALAN RAPAT PERMAI 18A
HDD	4.55777, 101.113134	4.559399, 101.112357	225	JALAN SULTAN NAZRIN SHAH
HDD	4.559399, 101.112357	4.561532, 101.112719	250	JALAN SULTAN NAZRIN SHAH
HDD	4.561532, 101.112719	4.563774, 101.113177	250	JALAN SULTAN NAZRIN SHAH
HDD	4.563774, 101.113177	4.565834, 101.11359	245	JALAN SULTAN NAZRIN SHAH
HDD	4.565834, 101.11359	4.568092, 101.113777	225	JALAN SULTAN NAZRIN SHAH
HDD	4.568092, 101.113777	4.569387, 101.113611	150	JALAN SULTAN NAZRIN SHAH
HDD	4.569387, 101.113611	4.570277, 101.115626	250	JALAN SULTAN NAZRIN SHAH
HDD	4.570277, 101.115626	4.571224, 101.117629	250	JALAN SULTAN NAZRIN SHAH
HDD	4.571224, 101.117629	4.572197, 101.119588	250	JALAN SULTAN NAZRIN SHAH
HDD	4.572197, 101.119588	4.573059, 101.121396	235	JALAN SULTAN NAZRIN SHAH
HDD	4.573059, 101.121396	4.574011, 101.123449	260	JALAN SULTAN NAZRIN SHAH
HDD	4.554655, 101.115673	4.556105, 101.114513	215	JALAN SULTAN NAZRIN SHAH
HDD	4.556105, 101.114513	4.55777, 101.113134	250	JALAN SULTAN NAZRIN SHAH
HDD	4.572221, 101.127191	4.571443, 101.129195	250	JALAN TEOH KIM SWEE
HDD	4.572999, 101.12512	4.572221, 101.127191	250	JALAN TEOH KIM SWEE
HDD	4.577716, 101.139773	4.577985, 101.140887	135	JALAN WIRA JAYA
HDD	4.577829, 101.138218	4.577716, 101.139773	180	JALAN WIRA JAYA
HDD	4.577985, 101.140887	4.576623, 101.141281	170	JLN DESA AMPANG 16
HDD	4.569108, 101.136901	4.569165, 101.138296	165	JLN PESIARAN WIRA JAYA 50
HDD	4.569165, 101.138296	4.571323, 101.13828	250	JLN PESIARAN WIRA JAYA 50
HDD	4.570175, 101.130983	4.56933, 101.132812	235	JLN PESIARAN WIRA JAYA 50
HDD	4.56933, 101.132812	4.568991, 101.134765	235	JLN PESIARAN WIRA JAYA 50
HDD	4.568991, 101.134765	4.569108, 101.136901	245	JLN PESIARAN WIRA JAYA 50
HDD	4.571443, 101.129195	4.570175, 101.130983	258	JLN PESIARAN WIRA JAYA 50
HDD	4.573447, 101.138227	4.575566, 101.138228	245	PESIARAN WIRA JAYA TIMUR 23
HDD	4.571323, 101.13828	4.573447, 101.138227	245	PESIARAN WIRA JAYA TIMUR 23
HDD	4.575566, 101.138228	4.577829, 101.138218	260	PESIARAN WIRA JAYA TIMUR 23

NOTA :

1. Sila rujuk dalam lampiran Borang Kelulusan Izin Lalu

CATATAN:


TANDATANGAN : PENGURUS KORIDOR NEGERI


Tarikh