



**ARAHAN KERJA**

**NO. ARAHAN KERJA**  
**WO-03-0249**

**TARIKH**  
**17.03.2025**

<b>ARAHAN DARI</b> KUDR	<b>VENDOR</b> AGF	<b>BAHAGIAN</b> PENGURUS OPERASI
----------------------------	----------------------	-------------------------------------

Kepada		Butiran Kerja		
ASIA GLOBAL FIELD SDN BHD		MEWUJUDKAN INTERCONNECTION ANTARA PMU TEMOH 132/33/11KV DENGAN SSU UTAR 33KV - (D-PZA-S19-1736)		
NO.	BUTIRAN	JARAK (M)		LOKASI
1	Mohon Atur Lawatan Tapak	<u>15010</u>		
	<b>Koordinat Mula</b>	<b>Koordinat Akhir</b>	<b>Jarak</b>	<b>Nama Jalan</b>
HDD	4.323352, 101.149592	4.318703, 101.148997	650	JALAN BUNGA RAYA, JALAN ANGGERIK & JALAN ANGKASA
OH	4.318703, 101.148997	4.31071, 101.150051	1100	JALAN ANGKASA, JALAN ANGASA 4, JALAN ANGKASA 5, SUNGAI KERANJI, JALAN BARU
OH	4.31071, 101.150051	4.310575, 101.149939	30	SUNGAI KERANJI
OH	4.310575, 101.149939	4.308829, 101.152677	400	SUNGAI KERANJI
HDD	4.308829, 101.152677	4.307644, 101.152892	140	JALAN IDRIS
OH	4.307644, 101.152892	4.305693, 101.151881	250	JALAN
HDD	4.305693, 101.151881	4.302767, 101.154694	470	JALAN STESEN
OH	4.302767, 101.154694	4.302402, 101.157627	370	JALAN STESEN, JALAN TEMBUSU
HDD	4.302402, 101.157627	4.298489, 101.16012	520	JALAN TEMOH
HDD	4.298489, 101.16012	4.298319, 101.160622	60	JALAN TEMOH
OH	4.298319, 101.160622	4.249132, 101.195539	7300	JALAN TEMOH
HDD	4.249132, 101.195539	4.249074, 101.195143	50	JALAN TEMOH
CW	4.249074, 101.195143	4.248081, 101.193681	300	PMU TEMOH 132/33/11KV
CW	4.336894, 101.14477	4.337339, 101.145434	100	UTAR
OH	4.337339, 101.145434	4.336049, 101.155718	1250	JALAN PERDANA
HDD	4.336049, 101.155718	4.335491, 101.15614	80	JALAN IPOH - KAMPAR
OH	4.335491, 101.15614	4.327019, 101.154376	1000	JALAN IPOH - KAMPAR
HDD	4.327019, 101.154376	4.326893, 101.153973	60	JALAN IPOH - KAMPAR
OH	4.326893, 101.153973	4.324609, 101.153374	300	JALAN IPOH - KAMPAR
HDD	4.324609, 101.153374	4.324079, 101.153385	70	KAMPAR SENTRAL
OH	4.324079, 101.153385	4.323352, 101.149592	510	JALAN BATU SINAR

**NOTA :**

- Sila rujuk dalam lampiran Pelan Izin Lalu

CATATAN:

-----  
-----  
-----

TANDATANGAN : PENGENGUS KORIDOR NEGERI

17.3.25

Tarikh



**ARAHAN KERJA**

**NO. ARAHAN KERJA**  
**WO-03-0249**

**TARIKH**  
**17.03.2025**

<b>ARAHAN DARI</b> KUDR	<b>VENDOR</b> KAD	<b>BAHAGIAN</b> GIS
----------------------------	----------------------	------------------------

Kepada		Butiran Kerja		
KUMPULAN ASIA DEBUT SDN BHD		MEWUJUDKAN INTERCONNECTION ANTARA PMU TEMOH 132/33/11KV DENGAN SSU UTAR 33KV - (D-PZA-S19-1736)		
NO.	BUTIRAN	JARAK (M)	LOKASI	
1	Mohon Sediakan Pelan Izin Lalu (PIL) dan data lot	<u>15010</u>		
	<b>Koordinat Mula</b>	<b>Koordinat Akhir</b>	<b>Jarak</b>	<b>Nama Jalan</b>
HDD	4.323352, 101.149592	4.318703, 101.148997	650	JALAN BUNGA RAYA, JALAN ANGGERIK & JALAN ANGKASA
OH	4.318703, 101.148997	4.31071, 101.150051	1100	JALAN ANGKASA, JALAN ANGASA 4, JALAN ANGKASA 5, SUNGAI KERANJI, JALAN BARU
OH	4.31071, 101.150051	4.310575, 101.149939	30	SUNGAI KERANJI
OH	4.310575, 101.149939	4.308829, 101.152677	400	SUNGAI KERANJI
HDD	4.308829, 101.152677	4.307644, 101.152892	140	JALAN IDRIS
OH	4.307644, 101.152892	4.305693, 101.151881	250	JALAN
HDD	4.305693, 101.151881	4.302767, 101.154694	470	JALAN STESEN
OH	4.302767, 101.154694	4.302402, 101.157627	370	JALAN STESEN, JALAN TEMBUSU
HDD	4.302402, 101.157627	4.298489, 101.16012	520	JALAN TEMOH
HDD	4.298489, 101.16012	4.298319, 101.160622	60	JALAN TEMOH
OH	4.298319, 101.160622	4.249132, 101.195539	7300	JALAN TEMOH
HDD	4.249132, 101.195539	4.249074, 101.195143	50	JALAN TEMOH
CW	4.249074, 101.195143	4.248081, 101.193681	300	PMU TEMOH 132/33/11kV
CW	4.336894, 101.14477	4.337339, 101.145434	100	UTAR
OH	4.337339, 101.145434	4.336049, 101.155718	1250	JALAN PERDANA
HDD	4.336049, 101.155718	4.335491, 101.15614	80	JALAN IPOH - KAMPAR
OH	4.335491, 101.15614	4.327019, 101.154376	1000	JALAN IPOH - KAMPAR
HDD	4.327019, 101.154376	4.326893, 101.153973	60	JALAN IPOH - KAMPAR
OH	4.326893, 101.153973	4.324609, 101.153374	300	JALAN IPOH - KAMPAR
HDD	4.324609, 101.153374	4.324079, 101.153385	70	KAMPAR SENTRAL
OH	4.324079, 101.153385	4.323352, 101.149592	510	JALAN BATU SINAR

**NOTA :**

- Sila rujuk dalam lampiran Borang Kelulusan Izin Lalu

CATATAN:

-----  
-----  
-----

TANDATANGAN : PENGURUS KORIDOR NEGERI

KORIDOR UTILITI DARUL RIDZUAN (KUDR)

17.3.25

Tarikh