



## ARAHAN KERJA

NO. ARAHAN KERJA  
**WO-01-26-0267**

TARIKH  
**30.06.2026**

<b>ARAHAN DARI</b> KUDR	<b>VENDOR</b> AGF	<b>BAHAGIAN</b> PENGURUS OPERASI
----------------------------	----------------------	-------------------------------------

Kepada		Butiran Kerja		
ASIA GLOBAL FIELD SDN BHD		MSVT (D-SIT-523-4782) PERMOHONAN BAGI MENDAPATKAN KEBENARAN MENJALANKAN KERJA MSVT MEWUJUDKAN 1 UNIT COMPACT SUB DI BAGAN PANCHOR BAGI MENGATASI MASALAH LOW VOLTAGE		
NO.	BUTIRAN	JARAK (M)		LOKASI
1	Mohon Atur Lawatan Tapak	<u>32</u>		
	<b>Koordinat Mula</b>	<b>Koordinat Akhir</b>	<b>Jarak</b>	<b>Nama Jalan</b>
HDD	4.52819, 100.644728	4.528329, 100.644829	11	JALAN BAGAN PANCHOR
HDD	4.52819, 100.644728	4.528351, 100.644549	21	JALAN BAGAN PANCHOR

**NOTA :**

- Sila rujuk dalam lampiran Pelan Izin Lalu

**CATATAN:**

-----  
-----  
-----  
-----

TANDATANGAN : PENGURUS KORIDOR NEGERI

1/7/2026

Tarikh



## ARAHAN KERJA

NO. ARAHAN KERJA  
**WO-01-26-0267**

TARIKH  
**30.06.2026**

ARAHAN DARI KUDR	VENDOR KAD	BAHAGIAN GIS
---------------------	---------------	-----------------

Kepada	Butiran Kerja
KUMPULAN ASIA DEBUT SDN BHD	MSVT (D-SIT-S23-4782) PERMOHONAN BAGI MENDAPATKAN KEBENARAN MENJALANKAN KERJA MSVT MEWUJUDKAN 1 UNIT COMPACT SUB DI BAGAN PANCHOR BAGI MENGATASI MASALAH LOW VOLTAGE

  

NO.	BUTIRAN	JARAK (M)	LOKASI
1	Mohon Sediakan Pelan Izin Lalu (PIL) dan data lot	<u>32</u>	
	<b>Koordinat Mula</b>	<b>Koordinat Akhir</b>	<b>Nama Jalan</b>
HDD	4.52819, 100.644728	4.528329, 100.644829	JALAN BAGAN PANCHOR
HDD	4.52819, 100.644728	4.528351, 100.644549	JALAN BAGAN PANCHOR

**NOTA :**

- Sila rujuk dalam lampiran Borang Kelulusan Izin Lalu

**CATATAN:**

-----  
-----  
-----

TANDATANGAN : PENGURUS KORIDOR NEGERI

1/7/2026

Tarikh